



Transistor / resistor verification





Radiant mode, 12mm gap, LA1@input, A@output, 7 power coils. Input +/-2amp
Probe 1: ground to negative of input battery, positive to collector transistor 1
Probe 2: ground not connected, positive to collector transistors 2,3,4,5,6,7



Transistor1 and 2





Transistor1 and 3




Transistor1 and 4



Transistor1 and 5 - x200



Transistor1 and 6



Transistor1 and 7

